



NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
[http://emnr.state.nm.us/ocd/District III/3district.htm](http://emnr.state.nm.us/ocd/District%20III/3district.htm)

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 7-11-2017 Operator Encana Oil/Gas API #30-0 43 - 21194

Property Name Lybrook K Well No. 0314 Location: Unit 111 Section 28 Township 23N Range 6W

Well Status (Shut-In or Producing) Initial PSI: Tubing 149 Intermediate 14 Casing 148 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE			FLOW CHARACTERISTICS	
	Bradenhead		INTERM	BRADENHEAD	INTERMEDIATE
	BH	Int	Csg	Int	Csg
TIME					
5 min	<u>0</u>	<u>N/A</u>	<u>148</u>		
10 min	<u>0</u>	<u>N/A</u>	<u>152</u>		
15 min	<u>0</u>	<u>N/A</u>	<u>152</u>	<u>N/A</u>	
20 min	<u>0</u>	<u>N/A</u>	<u>152</u>		
25 min	<u>0</u>	<u>N/A</u>	<u>152</u>		
30 min	<u>0</u>	<u>N/A</u>	<u>152</u>		
Steady Flow					
Surges					
Down to Nothing					
Nothing <u>X</u>					
Gas					
Gas & Water					
Water					

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR _____ FRESH _____ SALTY _____ SULFUR _____ BLACK _____

5 MINUTE SHUT-IN PRESSURE

BRADENHEAD 0

INTERMEDIATE N/A

REMARKS:

Compressor Down for maintenance
Left BH shut in

By Mary Stock
operator
(Position)

Witness _____

OIL CONS. DIV DIST. 3

JUL 14 2017

E-mail address greg.stock@encana.com