



NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
<http://emnr.state.nm.us/ocd/District/III3distric.htm>

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 7-7-17 Operator Encana Oil & Gas API #30-0 43-21197
Property Name North Flamito Unit Well No. 323H Location: Unit L Section 33 Township 23N Range 7W
Well Status (Shut-In or Producing) Initial PSI: Tubing 132 Intermediate N/A Casing 163 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing TIME	PRESSURE			INTERM	
	BH	Bradenhead Int Csg		Int	Csg
5 min	<u>0</u>	<u>N/A</u>	<u>163</u>		
10 min	<u>0</u>		<u>164</u>	<u>N</u>	
15 min	<u>0</u>		<u>159</u>		
20 min	<u>0</u>		<u>158</u>		
25 min	<u>0</u>		<u>161</u>		
30 min	<u>0</u>	<u>N/A</u>	<u>163</u>		

FLOW CHARACTERISTICS	
BRADENHEAD	INTERMEDIATE
Steady Flow	
Surges	
Down to Nothing	
Nothing	<u>X</u>
Gas	
Gas & Water	
Water	

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR _____ FRESH _____ SALTY _____ SULFUR _____ BLACK _____

5 MINUTE SHUT-IN PRESSURE

BRADENHEAD 0

INTERMEDIATE N/A

REMARKS:

Previous Name Lybrook L-33, Plugger running - left BH shut

By

Arthur Sullivan
Lead Tech
(Position)

Witness

OIL CONS. DIV DIST. 3
JUL 10 2017

E-mail address arthur.sullivan@encana.com