



NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
[http://emnrd.state.nm.us/ocd/District III/3district.htm](http://emnrd.state.nm.us/ocd/District%20III/3district.htm)

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 6-26-17 Operator FOUR STAR API #30-0 45-06876

Property Name NEAR VICTORIA Well No. 2 Location: Unit Section 1 Township 27 Range 9

Well Status(Shut-In or Producing) Initial PSI: Tubing 72 Intermediate Casing 75 Bradenhead 19

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE			INTERM	
	Bradenhead			Int	Csg
	BH	Int	Csg		
TIME					
5 min	<u>0</u>		<u>75</u>		
10 min	<u>0</u>		<u>75</u>		
15 min	<u>0</u>		<u>75</u>		
20 min					
25 min					
30 min					

FLOW CHARACTERISTICS
BRADENHEAD INTERMEDIATE

Steady Flow

Surges

Down to Nothing ✓

Nothing

Gas ✓

Gas & Water

Water

OIL CONS. DIV DIST. 3

JUL 17 2017

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR FRESH SALTY SULFUR BLACK

5 MINUTE SHUT-IN PRESSURE BRADENHEAD 17 INTERMEDIATE

REMARKS:

BLEW DOWN IN 4 SECONDS AFTER 5 MIN TEST
PRESSURE WENT BACK UP TO 17

By [Signature]
2101
(Position)

Witness

E-mail address