



NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
[http://emnrd.state.nm.us/ocd/District III3district.htm](http://emnrd.state.nm.us/ocd/District%20III3district.htm)

OIL CONS. DIV DIST. 3

JUL 13 2017

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 7-13-17 Operator Burlington API #30-0 45-23959
Property Name Patterson B Conn Well No. 1E Location: Unit Section 2 Township 31 Range 12
Well Status (Shut-In or Producing) Initial PSI: Tubing 136 Intermediate 1A Casing 68 Bradenhead 1

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE			INTERM	
	Bradenhead				
	BH	Int	Csg	Int	Csg
TIME					
5 min	<u>0</u>		<u>68</u>		
10 min	<u>0</u>		<u>68</u>		
15 min	<u>0</u>		<u>68</u>		
20 min					
25 min					
30 min					

FLOW CHARACTERISTICS	
BRADENHEAD	INTERMEDIATE
Steady Flow	
Surges	
Down to Nothing	<u>✓</u>
Nothing	
Gas	<u>✓</u>
Gas & Water	
Water	

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR FRESH SALTY SULFUR BLACK

5 MINUTE SHUT-IN PRESSURE

BRADENHEAD 0

INTERMEDIATE 1A

REMARKS:

Blew to dead at 3 seconds.
Nothing when opened after 5 min shut in

By [Signature]

(Position)

Witness Monica Cuchling

E-mail address