



NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
<http://emrnr.state.nm.us/ocd/District/III3district.htm>

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 7-14-2017 Operator Encana oil & Gas API #30-0 43-21208

Property Name Gallo Canyon well Well No. 20814 Location: Unit 0 Section 27 Township 23N Range 6W

Well Status(Shut-In or Producing) Initial PSI: Tubing 45 Intermediate N/A Casing 134 Bradenhead 1

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

PRESSURE

Testing	Bradenhead			INTERM	
	BH	Int.	Csg	Int	Csg
TIME					
5 min	<u>0</u>	<u>N/A</u>	<u>139</u>		
10 min	<u>0</u>	<u>N/A</u>	<u>139</u>		
15 min	<u>0</u>	<u>N/A</u>	<u>135</u>		
20 min	<u>0</u>	<u>N/A</u>	<u>135</u>	<u>N/A</u>	
25 min	<u>0</u>	<u>N/A</u>	<u>137</u>		
30 min	<u>0</u>	<u>N/A</u>	<u>136</u>		

FLOW CHARACTERISTICS
BRADENHEAD INTERMEDIATE

Steady Flow

Surges

Down to Nothing

Nothing

Gas

Gas & Water

Water

OIL CONS. DIV DIST. 3

If bradenhead flowed water, check all of the descriptions that apply below:

JUL 19 2017

CLEAR FRESH SALTY SULFUR BLACK

5 MINUTE SHUT-IN PRESSURE

BRADENHEAD

INTERMEDIATE

REMARKS:

Plunger Running - left BH shut IN

By Ding Stock
operator
(Position)

Witness

E-mail address greg.stock@encana.com