



NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
[http://emurd.state.nm.us/ocd/District III/district.htm](http://emurd.state.nm.us/ocd/District%20III/district.htm)

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 31-July-2017 Operator XD API #30-0 45-07894

Property Name MASDEN LLC Well No. #1 Location: Unit A Section 28 Township 29 Range 11

Well Status(Shut-In or Producing) Initial PSI: Tubing 8 Intermediate N/A Casing 19 Bradenhead 51

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE			INTERM	
	Bradenhead		Csg	Int	Csg
	BH	Int			
TIME					
5 min	<u>.5</u>	<u>N/A</u>	<u>19</u>		
10 min	<u>0</u>		<u>19</u>		
15 min	<u>0</u>		<u>19</u>		
20 min	<u>0</u>		<u>19</u>		
25 min	<u>0</u>		<u>19</u>		
30 min	<u>0</u>		<u>19</u>		

	FLOW CHARACTERISTICS	
	BRADENHEAD	INTERMEDIATE
Steady Flow		
Surges		
Down to Nothing	<u>X</u>	
Nothing		
Gas		
Gas & Water	<u>X</u>	
Water		

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR X FRESH _____ SALTY _____ SULFUR _____ BLACK _____

5 MINUTE SHUT-IN PRESSURE

BRADENHEAD 0

INTERMEDIATE N/A

REMARKS:

OPENED THE BRADENHEAD AND IT BLED
DOWN TO NOTHING IN 5 MINUTES MAKING 2 GALLONS OF

By CLARK Op
(Position)

Witness

[Signature]

OIL CONS. DIV DIST. 3
JUL 31 2017

E-mail address _____