NEW MEXICO ENERGY, MINERALS AND NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC, NM 87410
(505 334-6178 FAX: (505) 334-6170
http://www.emnrd.state.nm.us/ocd/

OIL CONS. DIV DIST. 3
AUG 09 2017

BRADENHEAD TEST REPORT

(Submit 2 copies to above address)

Date of Test 6.22.17 **Operator** BP America Production Company **API #** 3004523159

Property Name MUDGE LS 045-PC **Location:** Unit M Section 3 Township 31 Range 11

(Well Name and Number)

Pressure (Shut-in or Producing) Tubing N/A Intermediate N/A Casing 100.1 Bradenhead 58.2

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Time	Bradenhead: BH Blowdown	Bradenhead: Casing Monitor	Bradenhead: Intermediate Monitor	Intermediate: Intermediate Blowdown	Intermediate: Casing Monitor
5 minutes	Ø	100.2	N/A	N/A	N/A
10 minutes	Ø	99.2			
15 minutes	Ø	98.5			
20 minutes					
25 minutes					
30 minutes					
5 minute SI					

	Bradenhead Flowed	Intermediate Flowed
Steady Flow		N/A
Surges		
Down to Nothing	1 sec.	
No Flow	nothing after	
Gas		
Gas and Water		
Water		

If bradenhead flowed water, check all of the descriptions that apply below:

Clear _____ Fresh _____ Salty _____ Sulfur _____ Black _____

5 Minute Shut-in Bradenhead 13.7 Intermediate N/A

REMARKS: Slim hole design, pulled gas sample from BH + casing.

By Eugenia Hamilton
Lead Tech.
(Position)

Witness _____

NMOCD Test Area: A 1036