Form 3160-5 (August 2007)

UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

FORM APPROVED OMB No. 1004-0137 Expires: July 31, 2010

5. Lease Serial No.

N/IIA	02454	D	

			NM - 02151-B						
SUN	NDRY NOTICES AND REP	6. If Indian, Allottee or Tri	ibe Name						
Do not us	e this form for proposals	to drill or to re-enter an							
	well. Use Form 3160-3 (A								
	UBMIT IN TRIPLICATE - Other ins	7. If Unit of CA/Agreement, Name and/or No.							
1. Type of Well			San Juan 30-6 Unit						
Oil Well	X Gas Well Other		8. Well Name and No.						
			San	Juan 30-6 Unit 92					
2. Name of Operator			9. API Well No.						
	Hilcorp Energy Compa	any	3	0-039-07735					
3a. Address		3b. Phone No. (include area code)	10. Field and Pool or Expl	oratory Area					
PO Box 4700, Farmingt	on, NM 87499	505-599-3400		Blanco MV					
4. Location of Well (Footage, Sec., T.,1			11. Country or Parish, Stat						
	ENE), 1650' FNL & 1180' F	EI Soc 22 T20N D07W	Rio Arriba	. New Mexico					
Surface Unit H (S	ENE), 1050 FNL & 1100 F	EL, 3ec. 33, 130N, R07W	RIO ATTIDA	, New Mexico					
12. CHECK	THE APPROPRIATE BOX(ES)) TO INDICATE NATURE OF I	NOTICE, REPORT OR O	THER DATA					
TYPE OF SUPMISSION		TYPE OF /	ACTION						
TYPE OF SUBMISSION		TYPE OF A	ACTION						
Notice of Intent	Acidize	Deepen	Production (Start/Resume)	Water Shut-Off					
	Alter Casing	Fracture Treat	Reclamation	Well Integrity					
C I a D a d									
Subsequent Report	Casing Repair	New Construction	Recomplete	X Other FAN					
	Change Plans	Plug and Abandon	Temporarily Abandon						
X Final Abandonment Notice	Convert to Injection	Plug Back	Water Disposal						
-	was inspected and passe	mation was completed an ed on 8/15/17 with Bob Sw		ready for final closure this well from the Hilcorp					
		OIL CONS. DAV	DIST. 3	RECEIVED					
		SEP 1	2017	AUG 2 4 2017					
				Farmington Field Office Bureau of Land Management					
14. I hereby certify that the foregoing is	true and correct. Name (Printed/Type	ed)							
Christine Brock		Title Operations	Title Operations/Regulatory Technician						
Signature Ilhustu	in Brock	Date 8/23/	117						
	THIS SPACE FO	OR FEDERAL OR STATE O	FFICE USE						
Approved by		T							
Approved by			0	0 01 1					
Sun 6 A.	NA.	TOTAL	Sun NR	5 /25/12					
00 000080	had Approval of this paties de	Title	oceps vol	Date / 53/17					
Conditions of approval, if any, are attac	**	The second secon							
that the applicant holds legal or equitab	_	ase which would Office	660						
entitle the applicant to conduct operatio			1						
Title 18 U.S.C. Section 1001 and Title	43 U.S.C. Section 1212, make it a crim	ne for any person knowingly and willfu	ally to make to any department of	or agency of the United States any					

			N.>					· ···			
RCC Reclamation Completion			Location Name: 5 T 30-6 = ?	2	_		Date: 8-15-2017 Revision	3 (3/2	1/17)		
API#: 30 039 07735			UL-Sec-Twn-Rng: Sec 33 T301	Y A	974	J	Lat/Long: 36.77216 -107, 578	06	8		
Surface Owner: BLM			Lease# 62151-B County/State: RIO ARRIBA NEW			47	p	10			
Pipeline Owner:				Twin/Co-Locate Well Name & Operator:							-
1	Age	mev	Tuen	Gor: Contractor:				Seed Mix:			\dashv
Jan Javer			1	566 South							
Interim Reclamation	Completed	Incomplete	NIA	Final Reclamation	Completed	Incomplete		Remediation	Completed	Incomplete	N/A
Have pit sample results been approved				3rd party pipeline removed	V			Facilities stripped			
Has water been removed from pit				Anchors removed	11	Fig.		Certificate of waste issued & approved			
Have pit marker photos been taken				Equipment and piping removed	10	,		Depth:			
Has certificate of waste been issued & approved				Power poles removed	V			Width:			
Have all pit contents been removed				Cathodic protection removed	1			Length:			
Has sample after content removal been taken				Vegetative cages removed	V			Date of Excavation Start:			
Is location contoured				CMP's removed	V			Date of Excavation End:			
Is there 4' of cover over pit	1			Non native gravel buried or removed		ı		Date of Backfill Start:			
Has top soil been spread evenly				Noxious weeds removed or sprayed	-	-	/	Date of Backfill End:			
Has all non-native gravel been buried or removed				Insvasive weeds removed or sprayed	1			Yards Hauled Out:			
Has pit liner been removed				Contouring complete	10			Impacted Soil Hauled To:			
Has all trash been removed				Top soil spread	1			Yards Hauled In:			
Have all weeds been removed				Diversions clean and functional	1			Fresh Soll Hauled in From:			
Teardrop allows vehicle access to all facilities				Silt trap clean and functional	V			Approval to backfill			
Drainage ditches allow adequate run off				Cattle guard / gates removed		U	1	Back fill mechanically compacted			
All non-traffic areas disked properly				Cellar / mouse hole covered	V			Facilities reset			
All non-traffic areas seeded				Erosion under control	10		٦.	Trash and debri removed			
Seeded areas have been mulched				Location properly ripped	V		\neg	Close Out Completed			
Noxious weeds have been removed or sprayed				Location properly disked	V			Soil Removal Sundry Ready to be Filed	+		
Invasive weeds have been removed or sprayed				Location seeded	1				+-		
Barriers set to deter traffic	-		-	Photo transect installed	+				+		
Silt traps are functional	-	-		Access road properly closed		-	-		-	\vdash	-
Culverts are functional	-	_		Public use controlled	V	-	\dashv		-		\vdash
	-	_			V	-	\dashv	*	\perp		\vdash
Upper diversion is functional	-			Barriers in place	V	-	4		\perp		-
Erosion under control	-			Grazing controlled	V		4		1.		
Photo transect installed				P&A marker installed & legible	V					19.5	
Have wellhead cages and Jersey barriers been removed				Well sign removed	V	- 1	_		1	-	1.0
Have reclamation pictures been taken				Growth at least 70%	V				1	. ,4	
Growth at least 70%				Trash and debris removed from location	V					-	
Agency Inspection Date:				Final reclamation photos taken	V				1		
Sundry is ready to file				Agency Inspection Date: 8-15-2017				* .			
				FAN Ready to be filed				. 4.	121		
Remine Ry Anchor	S			Comments: Leady 70 FILE FAH		ν,		Comments:			

. ..

1