

## NEW MEXICO ENERGY, MINERALS & NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION AZTEC DISTRICT OFFICE 1000 RIO BRAZOS ROAD AZTEC NM 87410

(505) 334-6178 FAX: (505) 334-6170 http://emnrd.state.nm.us/ocd/District III/3distric.htm

## **BRADENHEAD TEST REPORT**

(submit 1 copy to above address)

· ·	
Date of Test Operato	r: Enervest Operating, LLC API #30-039-29839
Property Name: <u>Jicarilla A</u> Well No. 8N Location: Unit: <u>J_Section: 17 Township: 26N Range: 5W</u>	
Well Status(Shut-In or Producing) Initial PSI: Tubing Intermediate Casing 20 Bradenhead 0	
OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH	
PRESSURE Testing Bradenhead INTERM BH Int Csg Int Csg	FLOW CHARACTERISTICS BRADENHEAD INTERMEDIATE
TIME 5 min 0 170	Steady Flow
10 min 0 (20	Surges
15 min 0 20	Down to Nothing
20 min 0 12 J	Nothing
25 min 0 17 8	Gas
30 min 0 118	Gas & Water
Water	
If bradenhead flowed water, check all of the descriptions that apply below:	
CLEAR FRESH SALTY SULFUR BLACK	
5 MINUTE SHUT-IN PRESSURE BRADENHEAD O INTERMEDIATE	
REMARKS: No blow, Well flowing	
The state of the s	Witness
(Position)	THE STATE OF THE S
E-mail address runky Denervest. net	OIL CONS. DIV DIST. 3
- The state of the	SEP 05 2017