



NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
[http://emnrd.state.nm.us/ocd/District III3district.htm](http://emnrd.state.nm.us/ocd/District%20III3district.htm)

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 9-22-17 Operator BP America API #30-0 45-24735
Property Name GCU Well No. 328 Location: Unit N Section 33 Township 29 Range 12
Well Status (Shut-In or Producing) Initial PSI: Tubing 520 Intermediate N/A Casing 48 Bradenhead 4

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE				
	Bradenhead		INTERM		
	BH	Int	Csg	Int	Csg
TIME					
5 min	<u>0</u>		<u>52</u>		
10 min	<u>0</u>		<u>54</u>		
15 min	<u>0</u>		<u>57</u>		
20 min					
25 min					
30 min					

FLOW CHARACTERISTICS	
BRADENHEAD	INTERMEDIATE
Steady Flow	
Surges	
Down to Nothing	<u>✓</u>
Nothing	
Gas	<u>✓</u>
Gas & Water	
Water	

OIL CONS. DIV DIST. 3
SEP 22 2017

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR _____ FRESH _____ SALTY _____ SULFUR _____ BLACK _____

5 MINUTE SHUT-IN PRESSURE

BRADENHEAD 0

INTERMEDIATE N/A

REMARKS:

long puff to dead at 2 seconds. Puff when
opened after 5 min shut in

By Alan Brown
Well Intervention Team Leader
(Position)

Witness Marysa Kuehling

E-mail address _____