



NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
[http://emnr.state.nm.us/ocd/District III/3district.htm](http://emnr.state.nm.us/ocd/District%20III/3district.htm)

OIL CONS. DIV DIST. 3

SEP 27 2017

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 9-27-17 Operator Todd Lyford API #30-0 45 30293

Property Name Cwen Well No. 22 Location: Unit 19 Section 19 Township 31 Range 12

Well Status (Shut-In or Producing) Initial PSI: Tubing 23 Intermediate N/A Casing 27 Bradenhead 0.89

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE				
	Bradenhead		INTERM		
	BH	Int	Csg	Int	Csg
TIME					
5 min	<u>0</u>		<u>30</u>		
10 min	<u>0</u>		<u>30</u>		
15 min	<u>0</u>		<u>31</u>		
20 min					
25 min					
30 min					

FLOW CHARACTERISTICS	
BRADENHEAD	INTERMEDIATE
Steady Flow	
Surges	
Down to Nothing	<u>/</u>
Nothing	
Gas	<u>/</u>
Gas & Water	
Water	

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR FRESH SALTY SULFUR BLACK

5 MINUTE SHUT-IN PRESSURE

BRADENHEAD 0

INTERMEDIATE N/A

REMARKS:

dead at 3 seconds - attempted to get Gas
sample. clathring when opened after 5 min shut-in

By Jeremy Divine
Foreman
(Position)

Witness Mona Kuehling

E-mail address jdivine@crowneywest.com