

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
BUREAU OF LAND MANAGEMENT

RECEIVED

SEP 19 2017

FORM APPROVED  
OMB No. 1004-0137  
Expires: January 31, 2018

**SUNDRY NOTICES AND REPORTS ON WELLS**  
*Do not use this form for proposals to drill or to re-enter an abandoned well. Use Form 3160-3 (APD) for such proposals.*

Farmington Field Office  
Bureau of Land Management

5. Lease Serial No.  
**NOG14031948**

6. If Indian, Allottee or Tribe Name

7. If Unit of CA/Agreement, Name and/or No.  
**NMNM 135216A**

8. Well Name and No.  
**W Lybrook Unit 719H**

9. API Well No.  
**30-045-35812**

10. Field and Pool or Exploratory Area  
**Lybrook Mancos W**

11. Country or Parish, State  
**San Juan, NM**

**SUBMIT IN TRIPLICATE - Other instructions on page 2**

1. Type of Well  
 Oil Well     Gas Well     Other

2. Name of Operator  
**WPX Energy Production, LLC**

3a. Address  
**PO Box 640    Aztec, NM 87410**

3b. Phone No. (include area code)  
**505-333-1808**

4. Location of Well (Footage, Sec., T., R., M., or Survey Description)  
**SHL: 1846' FSL & 640' FEL Sec 14 T23N R9W Unit: I**  
**BHL: 330' FNL & 5' FWL Sec 14 T23N R9W Unit: D**

12. CHECK THE APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE, REPORT OR OTHER DATA

TYPE OF SUBMISSION	TYPE OF ACTION			
<input type="checkbox"/> Notice of Intent	<input type="checkbox"/> Acidize	<input type="checkbox"/> Deepen	<input type="checkbox"/> Production (Start/Resume)	<input type="checkbox"/> Water ShutOff
<input checked="" type="checkbox"/> Subsequent Report	<input type="checkbox"/> Alter Casing	<input type="checkbox"/> Hydraulic Fracturing	<input type="checkbox"/> Reclamation	<input type="checkbox"/> Well Integrity
<input type="checkbox"/> Final Abandonment Notice	<input type="checkbox"/> Casing Repair	<input type="checkbox"/> New Construction	<input type="checkbox"/> Recomplete	<input checked="" type="checkbox"/> Other <u>Final Casing</u>
<b>bl</b>	<input checked="" type="checkbox"/> Change Plans	<input type="checkbox"/> Plug and Abandon	<input type="checkbox"/> Temporarily Abandon	
	<input type="checkbox"/> Convert to Injection	<input type="checkbox"/> Plug Back	<input type="checkbox"/> Water Disposal	

13. Describe Proposed or Completed Operation: Clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof. If the proposal is to deepen directionally or recomplete horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports must be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a Form 3160-4 must be filed once testing has been completed. Final Abandonment Notices must be filed only after all requirements, including reclamation, have been completed and the operator has determined that the site is ready for final inspection.)

OIL CONS. DIV DIST. 3

SEP 22 2017

**9/15/17-** MIRU. PSI 7" Intermediate Casing, High 2,000 Psi for 30 Min: **All tested good and recorded on chart.** ✓

**9/16/17-** Drilling ahead 6-1/8" lateral. **TD 6-1/8" lateral @ 10920'** (TVD 4791').

**9/17-17-** Ran 124 Jts & 2 pup jts of 4.5" 11.6# P-110 LT&C CSG set @ 10916', LC @ 10868', RSI @ 10846', TOL @ 5346'.

"Cement 4.5", 5,000 Psi Test on Lines Flush Water @ 8.3# {10 BBLs}, followed by Tuned Spacer @ 11.5# {40 BBLs}, followed by Primary Cement @ 13.3# {127 Bbls/525 sks ExtendaCem ®} followed by Displacement Totaling 138 Bbls {40 Bbls MMCR & 98 Bbls of 2% KCL} Land Plug 1300 PSI & Bump up to 2700 PSI & Hold 5 min Floats Held got 1.5 Bbl Back on Bleed off Plug Down 9/17/2017 17:38hrs". "Set ZXP Pack off w/ 50 K, Pull up off and Quick Psi Test of Packer Seals with Pump Truck, Good Test, Sting out of Liner Hanger, W/ Pump truck Circ Out. 43 Bbl Good Cement to Surface"

**9/18/17-** Ran Tie Back Frac String, 120 jts & 4 pups of 4.5", 11.6# P-110, LT&C ✓

Pressure Test Tie Back Backside @ 2,000psi for 30 min, good test recorded on Antelope Services chart. & Secure Well. Rig Released @ 02:00 9/18/2017 ✓

Will report 4-1/2" test on completion paper work. ✓

ACCEPTED FOR RECORD

SEP 20 2017

14. I hereby certify that the foregoing is true and correct. Name (Printed/Typed)

Lacey Granillo

Title: Permit Tech

Signature



Date: 9/19/17

FARMINGTON FIELD OFFICE  
BY: [Signature]

**THE SPACE FOR FEDERAL OR STATE OFFICE USE**

Approved by	Title	Date
Conditions of approval, if any, are attached. Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease which would entitle the applicant to conduct operations thereon.	Office	

Title 18 U.S.C Section 1001 and Title 43 U.S.C Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

(Instructions on page 2)

NMOCDAV