



NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
[http://emnrd.state.nm.us/ocd/District II/3district.htm](http://emnrd.state.nm.us/ocd/District%20II/3district.htm)

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 10-20-17 Operator Coulthurst Mgt & Trw. API #30-0 43-20939
Property Name Erin Well No. 9 Location: Unit B Section 33 Township 18 Range 3
Well Status (Shut-In or Producing) Initial PSI: Tubing 12 Intermediate ✓A Casing 0 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE				
	BH	Bradenhead		INTERM	
		Int	Csg	Int	Csg
TIME					
5 min	<u>0</u>		<u>0</u>		
10 min	<u>0</u>		<u>0</u>		
15 min	<u>0</u>		<u>0</u>		
20 min					
25 min					
30 min					

FLOW CHARACTERISTICS	
BRADENHEAD	INTERMEDIATE
Steady Flow	
Surges	
Down to Nothing	
Nothing	<u>✓</u>
Gas	
Gas & Water	
Water	

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR _____ FRESH _____ SALTY _____ SULFUR _____ BLACK _____

5 MINUTE SHUT-IN PRESSURE

BRADENHEAD 0

INTERMEDIATE ✓A

REMARKS:

Nothing when opened - Nothing
when opened after 5 min shut in

By [Signature]
(Position)

Witness [Signature]

E-mail address _____