



NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
[http://emnr.state.nm.us/ocd/District III3distric.htm](http://emnr.state.nm.us/ocd/District%20III3district.htm)

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 10-31-17 Operator Robert L. Bayless API #30-0 45-30688
Property Name Hazel Bolack 10 Well No. 2 Location: Unit _____ Section 10 Township 30 Range 11
Well Status(Shut-In or Producing) Initial PSI: Tubing 15 Intermediate N/A Casing 40 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE					FLOW CHARACTERISTICS	
	Bradenhead		INTERM			BRADENHEAD	INTERMEDIATE
	BH	Int	Csg	Int	Csg		
TIME							
5 min	<u>0</u>		<u>40</u>			Steady Flow	
10 min	<u>0</u>		<u>40</u>			Surges	
15 min	<u>0</u>		<u>40</u>			Down to Nothing <u>✓</u>	
20 min						Nothing	
25 min						Gas <u>✓</u>	
30 min						Gas & Water	
						Water	

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR _____ FRESH _____ SALTY _____ SULFUR _____ BLACK _____

5 MINUTE SHUT-IN PRESSURE

BRADENHEAD 0

INTERMEDIATE N/A

REMARKS:

Light blow to dead at 3 seconds. Nothing
When opened after 5 min shut in

By BS
Production Foreman
(Position)

Witness Monica Kuehling

E-mail address _____