



NEW MEXICO ENERGY, MINERALS and NATURAL RESOURCES DEPARTMENT

OCT 26 2017

CONS. DIV DIST. 3

MECHANICAL INTEGRITY TEST REPORT

(TA OR UIC)

Date of Test 10/26/2017 Operator Hilcorp Energy API # 30-0 45-3793

Property Name LC Kelly Com Well # 100 Location: Unit A Sec 4 Twn 30 Rge 12

Land Type:

State _____
Federal X
Private _____
Indian _____

Well Type:

Water Injection _____
Salt Water Disposal _____
Gas Injection _____
Producing Oil/Gas X
Pressure observation _____

Temporarily Abandoned Well (Y/N): _____ TA Expires: _____

Casing Pres. 0
Crownhead Pres. 0
Tubing Pres. NA
Int. Casing Pres. NA

Tbg. SI Pres. NA
Tbg. Inj. Pres. NA

Max. Inj. Pres. NA

Pressured annulus up to 558 psi. for 30 mins. Test passed/failed

REMARKS: 1000 lbs spring, 1 hr clock, 1 hr 1000 lbs, start @ 0 psi, pressure up to 558 psi took a little more than 5 bbls to load, 5 min 557 psi BH 0 psi, 10 min 556 psi BH 0 psi, 15 min 555 psi BH 0 psi, 20 min 555 psi BH 0 psi, 25 min 555 psi BH 0 psi, 30 min 555 psi BH 0 psi, bleed back 0 psi. Recorder calibrated 10/24/2017

By R.E. [Signature]
(Operator Representative)

Witness [Signature]
(NMOCD)

Co Rep for Hilcorp
(Position)

Revised 02-11-02