



NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
[http://emnrd.state.nm.us/ocd/District III/3distric.htm](http://emnrd.state.nm.us/ocd/District%20III/3distric.htm)

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 10-31-17 Operator Robert H. Bayless API #30-0 45-32963

Property Name Hazel Bodack 10 Well No. 4 Location: Unit _____ Section 10 Township 30 Range 11

Well Status (Shut-In or Producing) Initial PSI: Tubing 20 Intermediate _____ Casing 35 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE				
	Bradenhead			INTERM	
	BH	Int	Csg	Int	Csg
TIME					
5 min	<u>0</u>		<u>35</u>		
10 min	<u>0</u>		<u>35</u>		
15 min	<u>0</u>		<u>35</u>		
20 min					
25 min					
30 min					

	FLOW CHARACTERISTICS	
	BRADENHEAD	INTERMEDIATE
Steady Flow		
Surges		
Down to Nothing	<u>✓</u>	
Nothing		
Gas	<u>✓</u>	
Gas & Water		
Water		

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR _____ FRESH _____ SALTY _____ SULFUR _____ BLACK _____

5 MINUTE SHUT-IN PRESSURE BRADENHEAD 0 INTERMEDIATE _____

REMARKS:

Duff when opened - nothing when
opened after 5 min shut in

By B. Bayless

Production Foreman

(Position)

Witness

Mona Lucking

E-mail address Bill@RLBayless.com