



NEW MEXICO ENERGY, MINERALS and NATURAL RESOURCES DEPARTMENT

MECHANICAL INTEGRITY TEST REPORT

(TA OR UIC)

Date of Test 10-18-17 Operator Lugan Rod. API # 30-0 45-33684

Property Name Monson SWD Well # 2 Location: Unit ___ Sec 13 Twn 22 Rge 9

Land Type:

State ___
Federal ___
Private ___
Indian ___

Well Type:

Water Injection ___
Salt Water Disposal ☒
Gas Injection ___
Producing Oil/Gas ___
Pressure observation ___

Temporarily Abandoned Well (Y/N): ___ TA Expires: ___

Casing Pres. 0
Bradenhead Pres. 0
Tubing Pres. 0
Int. Casing Pres. N/A

Tbg. SI Pres. ___
Tbg. Inj. Pres. ___

Max. Inj. Pres. ___

Pressured annulus up to 410 psi. for 30 mins. Test passed/failed

REMARKS:


Packer Set - 656
top of Tub 6254 - 6386
TID 6420

By [Signature]
(Operator Representative)

Witness [Signature]
(NMOCD)

(Position)

Revised 02-11-02



Graphic Controls

30-045-33684
CHART NO. MC MP-1000-IHR

METER _____ TAKEN OFF _____
CHART PUT ON _____
LOCATION Merrison #25m
REMARKS MIT
10/19/17

Monica Kullberg
Waco
Passed
10-19-17
Monica Kullberg