



NEW MEXICO ENERGY, MINERALS and NATURAL RESOURCES DEPARTMENT

MECHANICAL INTEGRITY TEST REPORT

(TA OR UIC)

Date of Test 10-19-17 Operator Lugan, Paul API # 30-0 45-35281

Property Name SE. Moritz SW 1/4 Well # 2 Location: Unit 26 Twn 24 Rge 10

Land Type:

State
Federal
Private
Indian

Well Type:

Water Injection
Salt Water Disposal ✓
Gas Injection
Producing Oil/Gas
Pressure observation

Temporarily Abandoned Well (Y/N): TA Expires:

Casing Pres. 0
Bradenhead Pres. 0
Tubing Pres. 0
Int. Casing Pres. N/A

Tbg. SI Pres.
Tbg. Inj. Pres.

Max. Inj. Pres.

Pressured annulus up to 400 psi. for 30 mins. Test passed/failed

REMARKS:


Packer Set 6803
for depth 6860
7077
TD 7200

By Lugan, Paul
(Operator Representative)

Witness Monica Trechling
(NMOCD)

(Position)

Revised 02-11-02



Graphic Controls

CHART NO. MC MP-1000-1HR
30-045-35281

METER _____

CHART PUT ON _____

262410

LOCATION _____

TAKEN OFF _____

REMARKS _____

St. Moritz #2560
MIT
10/19/17

M. K. M. K. M. K.
K. M. K. M. K.
K. M. K. M. K.
K. M. K. M. K.

10-18-17

James H. H.

PRINTED IN U.S.A.