



NEW MEXICO ENERGY, MINERALS and
NATURAL RESOURCES DEPARTMENT

MECHANICAL INTEGRITY TEST REPORT

(TA OR UIC)

Date of Test 11-2-17 Operator BP America API # 30-0 45-27340

Property Name NEBU Pump Mesa SW Well # 1 Location: Unit 36 Twn 31 Rge 8

Land Type:

State ✓
Federal
Private
Indian

OIL CONS. DIV DIST. 3

NOV 02 2017

Well Type:

Water Injection
Salt Water Disposal ✓
Gas Injection
Producing Oil/Gas
Pressure observation

Temporarily Abandoned Well (Y/N) (N) TA Expires:

Casing Pres. 0 Tbg. SI Pres. Max. Inj. Pres.
Bradenhead Pres. 0 Tbg. Inj. Pres.
Tubing Pres. N/A
Int. Casing Pres. 0

Pressured annulus up to 522 psi. for 30 40 mins. Test passed/failed

REMARKS: no tubing - Has work string
Two tests ran from PKI at 8025 to Surface. Failed
Third test ran from BP Set at 8065 to Surface
40 minute test - held at 503 for last 13 minutes =

Will need to do MIT retest when well put together - BHT & Kilck.

By Darabai Sun (Operator Representative) Witness Monica Kuehling (NMOCD)


(Position)

Revised 02-11-02

COMMENTS
 WSL NAME/SIGNATURE
 RIG OP. NAME/SIGNATURE
 TESTER NAME/SIGNATURE
 TEST COMPANY
 TEST EQUIP CALIBRATION
 HP PASS OR FAIL
 HP FALL OFF IN 5 MINUTES
 HP START TIME AND PRESSURE
 LP PASS OR FAIL
 LP FALL OFF IN 5 MINUTES
 LP START TIME AND PRESSURE
 WHAT IS BEING TESTED
 RIG NAME
 DATE

11/2/17
 New Pump Mover SWP #1
 DWS #30
 MIT Coating Test
 N/A
 N/A
 N/A
 520 psi
 510 psi
 38 mins
 5:00 pm
 5:38 pm
 -10 psi
 Pass
 2/21/17
 HIGH TECH RENTAL TOOLS
 Alfredo Santamaria-Garcia
 Dec 18/17

PRESSURE TEST CHART ANNOTATION
 CHART NO. MC MP-1000-1HR
 METER _____
 CHART PUT ON _____ M
 LOCATION _____
 REMARKS _____
 TAKEN OFF _____ M



30-045-27340