



NEW MEXICO ENERGY, MINERALS and NATURAL RESOURCES DEPARTMENT

OIL CONS. DIV DIST. 3

DEC 05 2017

MECHANICAL INTEGRITY TEST REPORT (TA OR UIC)

Date of Test 12-5-2017 Operator Hilcorp Energy API # 30-045-60060

Property Name Moore LS Well # 3 Location: Unit L Sec 13 Twn 32 Rge 12

Land Type:

State _____
Federal X
Private _____
Indian _____

Well Type:

Water Injection _____
Salt Water Disposal _____
Gas Injection _____
Producing Oil/Gas X
Pressure observation _____

Temporarily Abandoned Well NO Work over

TA Expires: _____

Casing Pres. Ø
Bradenhead Pres. Ø
Tubing Pres. Ø
Int. Casing Pres. _____

Tbg. SI Pres. _____
Tbg. Inj. Pres. _____

Max. Inj. Pres. _____

Pressured annulus up to 600 psi. for 30 mins. Test passed ~~failed~~

REMARKS: Pressured up to 600psi - had slight drop to approx 570 in first 15 min. Held at 585psi for the last 10 minutes of test

By [Signature]
(Operator Representative)

Witness [Signature]
(NMOCD)

(Position)

Revised 02-11-02

CIBP at test
* 4644' to surface new 4 1/2" st