

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

OIL CONS. DIV. DIST. 3
Submit 1 Copy to appropriate District Office in accordance with 19.15.29 NMAC.
DEC 26 2017

Form C-141
Revised April 3, 2017

Release Notification and Corrective Action

OPERATOR

Initial Report Final Report

Name of Company WPX Energy Production, LLC	Contact Deborah Watson
Address 721 S Main Ave, Aztec, NM	Telephone No. 505-333-1880
Facility Name W Lybrook Unit 720H	Facility Type Pipeline/ROW
Surface Owner Indian	Lease Information: NO-G1312-1862, NMNM 135216A
API No. 30-045-35818	

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
J	23	23N	09W	75	South	120	East	San Juan

Latitude: N36.205393 Longitude: W107.749757 NAD83

NATURE OF RELEASE

Type of Release Crude Oil	Volume of Release Estimated 15 BBL	Volume Recovered Estimated 3 BBL
Source of Release Failed Valve at Well Tie-In Riser	Date and Hour of Occurrence unknown	Date and Hour of Discovery 12/8/17
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Vanessa Fields/Cory Smith (NMOCD) Whitney Thomas (BLM-FFO), FIMO	
By Whom? Deborah Watson	Date and Hour 12/8/17, 14:42-14:46 followed by email 12/9 at 12:07	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse. N/A	
If a Watercourse was Impacted, Describe Fully.* N/A		
Describe Cause of Problem and Remedial Action Taken.* Bi-pass valve froze and cracked at well tie-in riser, the impacted area included the ROW and sagebrush field located W of the riser. Source was stopped, line emptied, release contained and cleanup initiated.		
Describe Area Affected and Cleanup Action Taken.* <ul style="list-style-type: none">Hydrovac/spec trucks called to location for fluid recovery.Stabilization of location and cleanup started on 12/8/2017. Crews repaired valve during week of 12/10/17. Crews removed impacted materials between 12/8-12/15. Impacted soil was taken to the landfarm for disposal.Following cleanup, 6 confirmation samples were collected from within the impacted area and analyzed for BTEX, and TPH (MRO/GRO/DRO). Confirmation samples were collected on 12/13/17-representatives from FIMO, NMOCD, and BLM were invited but not in attendance. One additional confirmation sample was collected on 12/15/17, a representative from BLM-FFO was in attendance during confirmation sampling on 12/15/17. Laboratory analytical results will be included with the Final C-141.Backfilling of the excavation occurred during the week of 12/18/17.		
I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.		

Signature: <i>Deborah Watson</i>	OIL CONSERVATION DIVISION	
Printed Name: Deborah Watson	Approved by Environmental Specialist <i>[Signature]</i>	
Title: Environmental Specialist	Approval Date: 1/2/2018	Expiration Date:
E-mail Address: Deborah.watson@wpxenergy.com	Conditions of Approval: <i>Follow Cleanup Action</i>	Attached <input type="checkbox"/>
Date: December 26, 2017 Phone: 505-333-1880	<i>NVF 1735236218</i>	

* Attach Additional Sheets If Necessary