

Submit 1 Copy To Appropriate District Office  
 District I – (575) 393-6161  
 1625 N. French Dr., Hobbs, NM 88240  
 District II – (575) 748-1283  
 811 S. First St., Artesia, NM 88210  
 District III – (505) 334-6178  
 1000 Rio Brazos Rd., Aztec, NM 87410  
 District IV – (505) 476-3460  
 1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
 Energy, Minerals and Natural Resources

Form C-103  
 Revised August 1, 2011

OIL CONSERVATION DIVISION  
 1220 South St. Francis Dr.  
 Santa Fe, NM 87505

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.) 1. Type of Well: Oil Well <input checked="" type="checkbox"/> Gas Well <input type="checkbox"/> Other <input type="checkbox"/>		WELL API NO. <b>30-045-35813</b>
2. Name of Operator <b>WPX Energy Production, LLC</b>		5. Indicate Type of Lease STATE <input type="checkbox"/> FEE <input type="checkbox"/>
3. Address of Operator <b>P. O. Box 640, Aztec, NM 87410 (505) 333-1808</b>		6. State Oil & Gas Lease No. <b>N0-G-1403-1948</b>
4. Well Location Unit Letter <b>I</b> : <b>1835'</b> feet from the <b>FSL</b> line and <b>624'</b> feet from the <b>FEL</b> line Section <b>14</b> Township <b>23N</b> Range <b>9W</b> NMPM County <b>San Juan</b>		7. Lease Name or Unit Agreement Name <b>NMNM 135216A</b>  <b>W Lybrook Unit</b>
		8. Well Number <b>716H</b>
		9. OGRID Number <b>120782</b>
		10. Pool name or Wildcat <b>Lybrook Mancos W</b>
		11. Elevation (Show whether DR, RKB, RT, GR, etc.) <b>6719' GR</b>

12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

<b>NOTICE OF INTENTION TO:</b> PERFORM REMEDIAL WORK <input type="checkbox"/> PLUG AND ABANDON <input type="checkbox"/> TEMPORARILY ABANDON <input type="checkbox"/> CHANGE PLANS <input type="checkbox"/> PULL OR ALTER CASING <input type="checkbox"/> MULTIPLE COMPL <input type="checkbox"/> DOWNHOLE COMMINGLE <input type="checkbox"/>  OTHER: <input type="checkbox"/>	<b>SUBSEQUENT REPORT OF:</b> REMEDIAL WORK <input type="checkbox"/> ALTERING CASING <input type="checkbox"/> COMMENCE DRILLING OPNS. <input type="checkbox"/> P AND A <input type="checkbox"/> CASING/CEMENT JOB <input type="checkbox"/>  OTHER: <b>INTER-WELL COMMUNICATION</b> <input checked="" type="checkbox"/>
---	--

13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

WPX Energy conducted a stimulation on the following well:

**NMOCD Order: R-14051**  
**Start date: 10/25/17**  
**End date: 11/1/17**  
**Type: Fracture Treatment**  
**Pressure: 6522psi**  
**Volume Average: Nitrogen – 31,558(scf); Sand – 6,416,200(lbs); Fluid – 1,275,722(gals)**  
**Results of any investigation conducted: N/A**

Attached: Spreadsheet with affected wells due to stimulation activity.

OIL CONS. DIV DIST. 3  
 JAN 12 2018

Spud Date:  Rig Release Date:

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Marie E. Florez TITLE Permit Tech DATE 1/12/17

Type or print name Marie E. Florez E-mail address: marie.jaramillo@wpxenergy.com PHONE: (505) 333-1808 For State Use Only

APPROVED BY: **Accepted For Record** TITLE \_\_\_\_\_ DATE \_\_\_\_\_  
 Conditions of Approval (if any): \_\_\_\_\_

### Affected Wells

Well Name	API number	Formation	Operator	Date Affected	Type Communication	Volume of Communication	Highest PSI Observed	Standard Operating PSI	Results of Communication	Results of any Investigation Conducted
W Lybrook Unit 712H	30-045-35776	Lybrook Mancos W	WPX	10/27/2017	Decrease production / increase water production	N/A	N/A	N/A	Shut in	No fluids or gas was released during these impacts
<b>Stimulated: W Lybrook Unit 716H</b>										