

OIL CONSERVATION DIVISION AZTEC DISTRICT OFFICE 1000 RIO BRAZOS ROAD **AZTEC, NM 87410** (505 334-6178 FAX: (505) 334-6170 http://www.emnrd.state.nm.us/ocd/

OIL CONS. DIV DIST. 3

JAN 02 2018

## **BRADENHEAD TEST REPORT**

(Submit 2 copies to above address)

(											
<b>Date of Test</b> 09/27/17		Operator		BP America Production		Company	NPI#	3004510258			
Property Name RIDDLE		RIDDLE C	LS 003-MV		Locatio	n: Unit N	Section 29 To	ownship 3	11	Range	9
(Well Name and Number)											
Pressure (Shut-in or Producing)     Tubing     73.9     Intermediate     0     Casing     73.8     Bradenhead     37.7											
OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH											
	Bradenhead				Interme	diate		Bradenhe	had	Interme	diate
Time	BH Blowdown	Casing Monitor	Intermediate Monitor		Intermediate Blowdown	Casing Monitor		Flowed		Flow	
5 minutes	0	74.1	0		0	73.2	Steady Flow				
10 minutes	0	74.3	0		0	72.4	Surges				
15 minutes	0	74.4	0	Ш	0	71.9	Down to Nothing	tes 58 s	1		
20 minutes							No Flow			no flo	W
25 minutes							Gas				
30 minutes							Gas and Water		_		
5 minute SI	1.2				0		Water				
If bradenhead flowed water, check all of the descriptions that apply below:   Clear Fresh Salty Sulfur Black   REMARKS:											
By Scott Willard Witness											