NEW MEXICO ENERGY, MINERALS AND NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC, NM 87410
(505 334-6178 FAX: (505) 334-6170
http://www.emnrd.state.nm.us/ocd/

OIL CONS. DIV DIST. 3

JAN 02 2018

BRADENHEAD TEST REPORT

(Submit 2 copies to above address)

Date of Test 08/10/17 **Operator** BP America Production Company **API #** 3004522147

Property Name **FLORANCE GC D 004A-MV** **Location:** Unit C Section 10 Township 30 Range 9

(Well Name and Number)

Pressure (Shut-in or Producing) Tubing 52.2 Intermediate _____ Casing 56.1 Bradenhead 32.8

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Time	Bradenhead			Intermediate	
	BH Blowdown	Casing Monitor	Intermediate Monitor	Intermediate Blowdown	Casing Monitor
5 minutes	0	57.9			
10 minutes	0	57.3			
15 minutes	0	56.8			
20 minutes					
25 minutes					
30 minutes					
5 minute SI	0				

	Bradenhead Flowed	Intermediate Flowed
Steady Flow		
Surges		
Down to Nothing	45 sec	
No Flow		
Gas		
Gas and Water		
Water		

If bradenhead flowed water, check all of the descriptions that apply below:

Clear _____ Fresh _____ Salty _____ Sulfur _____ Black _____

REMARKS:

Compressor on location running casing closed pulled gas samples on BH string tubing string and casing string.

By Matthew Yazzie **Witness** _____

NMOCD Test Area: A