## State of New Mexico Energy, Minerals and Natural Resources Department

**Susana Martinez** Governor Ken McQueen Heather Riley, Division Director **Cabinet Secretary Oil Conservation Division Matthias Sayer Deputy Cabinet Secretary** New Mexico Oil Conservation Division approval and conditions listed below are made in accordance with OCD Rule 19.15.7.11 and are in addition to the actions approved by BLM on the following 3160-4 or 3160-5 form. Operator Signature Date: 1/16/18 Well information: API WELL Well Well Name Type Stat County Surf\_Owner **Operator Name** 30-045-NORTHEAST BLANCO 003H BP AMERICA San 35829-00-00 UNIT 604 COM PRODUCTION Juan COMPANY Application Type: □ Drilling/Casing Change □ Location Change P&A Recomplete/DHC (For hydraulic fracturing operations review EPA Underground injection control Guidance #84: Submit Gas Capture Plan form prior to spudding or initiating recompletion operations) Other: Conditions of Approval: Perform a CBL to verify the Top of Cement in the production casing and submit it to the agencies for review and approval.

NMOCD Approved by Signature

2/6/18 Date Form 3160-5 (June 2015)

# UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

FORM APPROVED OMB NO. 1004-0137 Expires: January 31, 2018

| SUNDRY NOTICES AND REPORTS ON WELLS   |                           |                                 |           | NMNM03358  |                            |
|---|---------------------------|---------------------------------|-----------|--|----------------------------|
| Do not use this form for proposals to drill or to re-enter an abandoned well. Use form 3160-3 (APD) for such proposals.   |                           |                                 |           | 6. If Indian, Allottee or Tribe Name                   |                            |
| SUBMIT IN TRIPLICATE - Other instructions on page 2   |                           |                                 |           | 7. If Unit or CA/Agreement, Name and/or No. NMNM137683 |                            |
| Type of Well     Oil Well   |                           |                                 |           | 8. Well Name and No.<br>NEBU 604 COM 3H                |                            |
| 2. Name of Operator Contact: TOYA COLVIN BP AMERICA PRODUCTION COMPASI-Mail: Toya.Colvin@bp.com   |                           |                                 |           | 9. API Well No.<br>30-045-35829-00-X1                  |                            |
| 3a. Address 501 WESTLAKE PARK BLVD. THREE ELDRIGE PLACE: 281.892.5369 HOUSTON, TX 77079   |                           |                                 |           | 10. Field and Pool or Exploratory Area BASIN MANCOS    |                            |
| 4. Location of Well (Footage, Sec., T., R., M., or Survey Description)  |                           |                                 |           | 11. County or Parish, State                            |                            |
| Sec 13 T31N R7W SWNW 1910FNL 587FWL 36.901531 N Lat, 107.529266 W Lon   |                           |                                 |           | SAN JUAN COUNTY, NM                                    |                            |
| 12. CHECK THE AP  | PROPRIATE BOX(ES) TO IN   | NDICATE NATURE OF               | F NOTICE, | REPORT, OR OTH   | ER DATA                    |
| TYPE OF SUBMISSION  | TYPE OF ACTION            |                                 |           |  |                            |
| ☐ Notice of Intent  | ☐ Acidize                 | ☐ Deepen ☐ Prod                 |           | ion (Start/Resume)                                     | ■ Water Shut-Off           |
| _   | ☐ Alter Casing            | ☐ Hydraulic Fracturing ☐ Reclan |           | ation  | ■ Well Integrity           |
| Subsequent Report   | ☐ Casing Repair           | ■ New Construction              |           |  | <b>⊘</b> Other             |
| ☐ Final Abandonment Notice  | ☐ Change Plans            | □ Plug and Abandon              |           |  | <b>Drilling Operations</b> |
|   | ☐ Convert to Injection    | ☐ Plug Back                     | ack       |  |                            |
| Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports must be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a Form 3160-4 must be filed once testing has been completed. Final Abandonment Notices must be filed only after all requirements, including reclamation, have been completed and the operator has determined that the site is ready for final inspection.  Please see the attached production casing report for the subject well.  NMNM137683  9 5/8" Casing MIT Also Attached. |                           |                                 |           |  |                            |
| 14. I hereby certify that the foregoing is true and correct.  |                           |                                 |           |  |                            |
| Electronic Submission #400979 verified by the BLM Well Information System For BP AMERICA PRODUCTION COMPANY, sent to the Farmington Committed to AFMSS for processing by JACK SAVAGE on 01/17/2018 (18JWS0088SE)  |                           |                                 |           |  |                            |
|   | ,                         |                                 |           |  |                            |
| Name (Printed/Typed) TOYA COLVIN Title REGULATORY ANALYST   |                           |                                 |           |  |                            |
| Signature (Electronic Submission) Date 01/16/2018   |                           |                                 |           |  |                            |
|   | THIS SPACE FOR FE         | DERAL OR STATE (                | OFFICE U  | SE   |                            |
| Approved By ACCEPT  | JACK SAV.<br>TitlePETROLE |                                 | EER       | Date 01/17/2018  |                            |
| Conditions of approval, if any, are attached certify that the applicant holds legal or equivalent would entitle the applicant to conductive the applicant to conductive the applicant to conductive the applicant to conduct  | t lease                   | Office Farmington               |           |  |                            |
| Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.  |                           |                                 |           |  |                            |
| (Instructions on page 2) ** BLM REVISED ** BLM REVISED ** BLM REVISED ** BLM REVISED **   |                           |                                 |           |  |                            |

#### PRODUCTION DRILLING OPS Report for the NEBU 604 Com 3H

#### December 2017- January 2018

12/21/2017- 9 5/8" CASING MIT 1500 PSI 30 MINS- PASSED-- ATTACHED

12/22/2017-\_1/11/2018- DRILL PRODUCTION CURVE, <u>DIR DRILL</u> 8-3/4" PROD1 HOLE TO 7,295', DIR DRILL 8-3/4" PROD1 HOLE F/ 7,295' TO 7,753' MD, DIR DRILL 8-3/4" PROD1 HOLE F/ 7,753' TO 7,807', DIR DRILL 8-3/4" PROD1 HOLE F/ 7,753' TO 7,807', DIR DRILL 8-3/4" PROD1 HOLE F/ 8,105' TO 11,951' MD, DIR DRILL 8-3/4" PROD1 HOLE F/ 11,951' TO 12,436' MD, DIR DRILL 8-3/4" PROD1 HOLE F/ 12,436' TO 13,162' MD, DIR DRILL 8-3/4" PROD1 HOLE F/ 13,253' TO 13,253' MD, DIR DRILL 8-3/4" PROD1 HOLE F/ 14,552' TO 15,500' MD, DIR DRILL 8-3/4" PROD1 HOLE F/ 16,443' TO 17,388' TD

01/12/2018- 01/14/2018- R/U AND RUN 5 1/2" 20# P-110 PRODUCTION CASING TO TD @ 17352'

01/15/2018- PUMP PRODUCTION CEMENT JOB AS FOLLOWS:
-TUNED SPACER - 60 BBLS, 12.8 PPG W/ RA TAG TRACER IN
LAST PART OF SLURRY
-TAIL CEMENT- 2715 SXS, 13.3 PPG YIELD 1.36, 657.6 BBLS SLURRY
-DROP LATCH PLUG
-DISPLACE W/ 40 BBLS SPACER W/ MICRO RETARDER @ 8.33
PPG
-DISPLACE W/ 338 BBLS DISPLACEMENT @ 8.33 PPG
-LANDED PLUG AT 2200 PSI & PRESSURED UP TO 3100 FOR 5
MIN
-CHECKED FLTS, 4.5 BBLS RETURNED, FLOATS HELD
FULL RETURNS THROUGHOUT JOB. VERY GOOD LIFT

PRESSURE CONSISTENT WITH JOB MODEL INDICATING TOC ~2900' MD

RELEASE RIG @ 1600 HRS V

### NEBU 604 COM 3H AZTEC 1000

Page 1/1

