



NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
[http://emnr.state.nm.us/ocd/District III/3district.htm](http://emnr.state.nm.us/ocd/District%20III/3district.htm)

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 4-3-2018 Operator Agua Moss API #30-0 45-28653

Property Name Sunco Disposal Well No. 1 Location: Unit E Section 2 Township 29 Range 12

Well Status (Shut-In or Producing) Initial PSI: Tubing 1400 Intermediate NA Casing 0 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE			INTERM	
	BH	Bradenhead Int	Csg	Int	Csg
TIME					
5 min	<u>0</u>	<u>NA</u>	<u>0</u>		
10 min	<u>0</u>	<u>0</u>	<u>0</u>		
15 min	<u>0</u>	<u>0</u>	<u>0</u>		
20 min	<u>0</u>	<u>0</u>	<u>0</u>		
25 min	<u>0</u>	<u>0</u>	<u>0</u>		
30 min	<u>0</u>	<u>0</u>	<u>0</u>		

	FLOW CHARACTERISTICS	
	BRADENHEAD	INTERMEDIATE
Steady Flow		
Surges		
Down to Nothing		
Nothing - <u>vac</u>		
Gas		
Gas & Water		
Water		

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR _____ FRESH _____ SALTY _____ SULFUR _____ BLACK _____

5 MINUTE SHUT-IN PRESSURE

BRADENHEAD 0

INTERMEDIATE NA

REMARKS:

BH had slight vac. when opened. Nothing on BH after 5 min shut-in.

By [Signature]
Manager
(Position)

Witness [Signature] NMOC

E-mail address _____