

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
BUREAU OF LAND MANAGEMENT

RECEIVED

FORM APPROVED  
OMB No. 1004-0137  
Expires: July 31, 2010

MAP 22 2018

5. Lease Serial No. **SF-078464**

6. If Indian, Allottee or Tribe Name

**SUNDRY NOTICES AND REPORTS ON WELLS**  
*Do not use this form for proposals to drill or to re-enter an abandoned well. Use Form 3160-3 (APD) for such proposals.*

Farmington Field Office  
Bureau of Land Management

SUBMIT IN TRIPLICATE - Other instructions on page 2.

7. If Unit of CA/Agreement, Name and/or No.

1. Type of Well  
 Oil Well  Gas Well  Other

8. Well Name and No. **Federal A 1E**

2. Name of Operator **Hilcorp Energy Company**

9. API Well No. **30-045-34486**

3a. Address **PO Box 4700, Farmington, NM 87499**

3b. Phone No. (include area code) **505-599-3400**

10. Field and Pool or Exploratory Area **Basin Dakota**

4. Location of Well (Footage, Sec., T., R., M., or Survey Description) **Surface Unit L (NWSW), 1660' FSL & 765' FWL, Sec. 25, T31N, R13W**

11. Country or Parish, State **San Juan, New Mexico**

12. CHECK THE APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE, REPORT OR OTHER DATA

ack

TYPE OF SUBMISSION		TYPE OF ACTION				
<input type="checkbox"/> Notice of Intent	<input type="checkbox"/> Acidize	<input type="checkbox"/> Deepen	<input type="checkbox"/> Production (Start/Resume)	<input type="checkbox"/> Water Shut-Off		
<input checked="" type="checkbox"/> Subsequent Report	<input type="checkbox"/> Alter Casing	<input type="checkbox"/> Fracture Treat	<input type="checkbox"/> Reclamation	<input type="checkbox"/> Well Integrity		
<input type="checkbox"/> Final Abandonment Notice	<input type="checkbox"/> Casing Repair	<input type="checkbox"/> New Construction	<input type="checkbox"/> Recomplete	<input checked="" type="checkbox"/> Other <u>Interim Reclamation</u>		
	<input type="checkbox"/> Change Plans	<input type="checkbox"/> Plug and Abandon	<input type="checkbox"/> Temporarily Abandon			
	<input type="checkbox"/> Convert to Injection	<input type="checkbox"/> Plug Back	<input type="checkbox"/> Water Disposal			

13. Describe Proposed or Completed Operation: Clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof. If the proposal is to deepen directionally or recomplate horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports must be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a Form 3160-4 must be filed once Testing has been completed. Final Abandonment Notices must be filed only after all requirements, including reclamation, have been completed and the operator has determined that the site is ready for final inspection.)

**Hilcorp Energy Company conducted a legacy interim reclamation inspection on 2/27/2018 with BLM Inspector Bob Switzer and received approval for the reclamation BMPs on the subject well.**

NMOCD  
APR 06 2018  
DISTRICT III

14. I hereby certify that the foregoing is true and correct. Name (Printed/Typed) **Christine Brock** Title **Operations/Regulatory Technician**  
Signature *Christine Brock* Date **3/22/2018**

THIS SPACE FOR FEDERAL OR STATE OFFICE USE

Approved by *Supervisor* Title **Supervisor** Date **4/2/18**  
Office **RF0**

Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

RCC Reclamation Completion		Location Name: <u>Federal A 1E</u>		Date: <u>2/27/18</u> <small>Revision 3 (3/21/17)</small>	
AP#: <u>30-045-34486</u>		UL-Sec-Twn-Rng: <u>L-25-031N-013W</u>		Lat/Long: <u>36.868238 -108.161360</u>	
Surface Owner: <u>BLM</u>		Lease# <u>SF-078464</u>		County/State: <u>San Juan County</u>	
Pipeline Owner: <u>ENT</u>		Twin/Co-Locate Well Name & Operator:			
Onsite: <u>Eric Smith</u>		Agency Inspector: <u>Bob Switzer</u>		Contractor:	
Seed Mix:					
Interim Reclamation		Final Reclamation		Remediation	
Have pit sample results been approved	Completed	Completed	Completed	Completed	Completed
Has water been removed from pit		3rd party pipeline removed		Facilities stripped	
Have pit marker photos been taken		Anchors removed		Certificate of waste issued & approved	
Has certificate of waste been issued & approved		Equipment and piping removed		Depth:	
Have all pit contents been removed		Power poles removed		Width:	
Has sample after content removal been taken		Cathodic protection removed		Length:	
Is location contoured		Vegetative cages removed		Date of Excavation Start:	
Is there 4" of cover over pit		CMP's removed		Date of Excavation End:	
Has top soil been spread evenly		Non native gravel buried or removed		Date of Backfill Start:	
Has all non-native gravel been buried or removed		Noxious weeds removed or sprayed		Date of Backfill End:	
Has pit liner been removed		Invasive weeds removed or sprayed		Yards Hauled Out:	
Has all trash been removed		Contouring complete		Impacted Soil Hauled To:	
Have all weeds been removed		Top soil spread		Yards Hauled In:	
Teardrop allows vehicle access to all facilities		Diversions clean and functional		Fresh Soil Hauled In From:	
Drainage ditches allow adequate run off		Silt trap clean and functional		Approval to backfill	
All non-traffic areas disked properly		Cattle guard / gates removed		Back fill mechanically compacted	
All non-traffic areas seeded		Cellar / mouse hole covered		Facilities reset	
Seeded areas have been mulched		Erosion under control		Trash and debris removed	
Noxious weeds have been removed or sprayed		Location properly ripped		Close Out Completed	
Invasive weeds have been removed or sprayed		Location properly disked		Soil Removal Sundry Ready to be Filed	
Barriers set to deter traffic		Location seeded			
Silt traps are functional		Photo transect installed			
Culverts are functional		Access road properly closed			
Upper diversion is functional		Public use controlled			
Erosion under control		Barriers in place			
Photo transect installed		Grazing controlled			
Have wellhead cages and jersey barriers been removed		P&A marker installed & legible			
Have reclamation pictures been taken		Well sign removed			
Growth at least 70%		Growth at least 70%			
Agency Inspection Date: <u>2/27/18</u>		Trash and debris removed from location			
Sundry is ready to file		Final reclamation photos taken			
		Agency Inspection Date:			
		FAN Ready to be filed			
Comments:		Comments:		Comments:	

Federal A 1E

36 868238 - 108 161360  
FEDERAL A # 1E

Google Earth

© 2018 Google

