



NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
[http://emrdd.state.nm.us/ocd/District III3district.htm](http://emrdd.state.nm.us/ocd/District%20III3district.htm)

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 3-22-18 Operator ENDURING RESOURCES API # 30-045-24392

Property Name CARDON COM Well No. SWD 1 Location: Unit Section 27 Township 32N Range 13W

Well Status (Shut-In or Producing) Initial PSI: Tubing -550 Intermediate 59 Casing -5 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE			INTERM	
	BH	Int	Csg	Int	Csg
TIME					
5 min	0	59	-5	0	-4
10 min	0	59	-5	0	-4
15 min	0	59	-4	0	-4
20 min					
25 min					
30 min					

FLOW CHARACTERISTICS	
BRADENHEAD	INTERMEDIATE
Steady Flow	
Surges	
Down to Nothing	✓
Nothing	✓
Gas	✓
Gas & Water	
Water	

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR FRESH SALTY SULFUR BLACK

5 MINUTE SHUT-IN PRESSURE BRADENHEAD 0 INTERMEDIATE 0

REMARKS:

INT BLOWN DOWN IN 30 SEC.
NO GAS ANALYSIS ON CASING & Intermediate

By [Signature]
AIR QUALITY SPECIALIST
(Position)

Witness [Signature]

E-mail address skarrette@enduringresources.com

NMOCD
APR 18 2018
DISTRICT III