



NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410

(505) 334-6178 FAX: (505) 334-6170
[http://emnr.state.nm.us/ocd/District III/3district.htm](http://emnr.state.nm.us/ocd/District%20III/3district.htm)

NMOCO
APR 26 2018
DISTRICT III

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 4-27-18 Operator H. Corp API #30-0 439-07777
Property Name Sun Juan 306 let Well No. 78 Location: Unit 25 Section 25 Township 30 Range 7
Well Status (Shut-In or Producing) Initial PSI: Tubing 180 Intermediate -1 Casing 180 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE			INTERM	
	BH	Int	Csg	Int	Csg
TIME					
5 min	0	-1	180	0	180
10 min	0	-1	180	0	180
15 min	0	-1	180	0	180
20 min					
25 min					
30 min					

	FLOW CHARACTERISTICS	
	BRADENHEAD	INTERMEDIATE
Steady Flow		
Surges		
Down to Nothing		
Nothing	/	/
Gas		
Gas & Water		
Water		

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR _____ FRESH _____ SALTY _____ SULFUR _____ BLACK _____

5 MINUTE SHUT-IN PRESSURE

BRADENHEAD 0 INTERMEDIATE 0

REMARKS:

Nothing when opened. Nothing when opened
after 5 min shut-in. Int Nothing when opened.
Nothing when opened after 5 min shut-in

By Brent Hottell ALT

Witness Monica Fuchling

(Position)

E-mail address _____