



NEW MEXICO ENERGY, MINERALS and NATURAL RESOURCES DEPARTMENT

NMOCD

APR 26 2018

DISTRICT III

MECHANICAL INTEGRITY TEST REPORT

(TA OR UIC)

Date of Test 4-27-18 Operator Hilltop Energy Co API # 30-0 39-24867

Property Name San Juan 30-6 Unit Well # 488 Location: Unit B Sec 24 Twn 30 Rge 6

Land Type:

State _____
Federal ☒ _____
Private _____
Indian _____

Well Type:

Water Injection _____
Salt Water Disposal _____
Gas Injection _____
Producing Oil/Gas _____
Pressure observation _____

Temporarily Abandoned Well (Y/N): _____ TA Expires: 4-27-2023

Casing Pres. 0 Tbg. SI Pres. _____ Max. Inj. Pres. _____
Bradenhead Pres. 0 Tbg. Inj. Pres. _____
Tubing Pres. 511A
Int. Casing Pres. 511A

Pressured annulus up to 570 psi. for 30 mins. Test passed/failed

REMARKS:

dropped to 562 - held.

bridgport Ducka Set 2840

top pay 2925

By EJ 314
(Operator Representative)

Witness Melissa Kuchling
(NMOCD)

LEAD OPERATOR
(Position)

Revised 02-11-02