



NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
[http://emnr.state.nm.us/ocd/District III/3dlatric.htm](http://emnr.state.nm.us/ocd/District%20III/3dlatric.htm)

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 4-16-18 Operator RIM API #30-0 45-08854

Property Name Southern Union Well No. 1 Location: Unit B Section 3 Township 29 Range 13

Well Status (Shut-In or Producing) Initial PSI: Tubing 100 Intermediate Casing 360 Bradenhead 15

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE			INTERM	
	BH	Int	Csg	Int	Csg
TIME					
5 min	0		360		
10 min	0		360		
15 min	0		360		
20 min					
25 min					
30 min					

FLOW CHARACTERISTICS	
BRADENHEAD	INTERMEDIATE
Steady Flow	
Surges	
Down to Nothing	X
Nothing	
Gas	X
Gas & Water	
Water	

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR FRESH SALTY SULFUR BLACK

5 MINUTE SHUT-IN PRESSURE

BRADENHEAD 0 INTERMEDIATE

REMARKS:

By Burt Ellick

Witness

(Position)

Pumper

E-mail address

NMOC
MAY 04 2018
DISTRICT III