



NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
[http://emrwd.state.nm.us/ocd/District III/3dDistrict.htm](http://emrwd.state.nm.us/ocd/District%20III/3dDistrict.htm)

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 4-9-2018 Operator Rim API #30-0 215-23452

Property Name Chili Agy State Well No. 1 Location: Unit C Section 16 Township 27 Range 12-W

Well Status(Shut-In or Producing) Initial PSI: Tubing 8 Intermediate 116 Casing 8 Bradenhead 2

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE			INTERM	
	Bradenhead			Int	Csg
	BH	Int	Csg		
TIME					
5 min	<u>0</u>	<u>1</u>	<u>8</u>		
10 min	<u>0</u>	<u>1</u>	<u>8</u>		
15 min	<u>0</u>	<u>1</u>	<u>8</u>		
20 min					
25 min					
30 min					

FLOW CHARACTERISTICS	
BRADENHEAD	INTERMEDIATE
Steady Flow	
Surges	
Down to Nothing	<u>X</u>
Nothing	
Gas	
Gas & Water	
Water	

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR _____ FRESH _____ SALTY _____ SULFUR _____ BLACK _____

5 MINUTE SHUT-IN PRESSURE

BRADENHEAD 0

INTERMEDIATE _____

REMARKS:

By Daryl Wright

Witness _____

(Position)

E-mail address _____

NOVCD
MAY 04 2018
DISTRICT III