



NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
<http://emnr.state.nm.us/ocd/DistrictIII/district.htm>

NMOCD

MAY 25 2018

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

DISTRICT III

Date of Test 5/25/2018 Operator Logos API #30-0 39-07958
Property Name Rosa Unit Well No. 14 Location: Unit B Section 23 Township 31 Range 6
Well Status (Shut-In or Producing) Initial PSI: Tubing 94 Intermediate -0.2 Casing 139 Bradenhead -0.3

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE				
	BH	Int	Csg	Int	Csg
TIME					
5 min	0	0	140	0	141
10 min	0	0	140	0	141
15 min	0	0	140	0	141
20 min					
25 min					
30 min					

	FLOW CHARACTERISTICS	
	BRADENHEAD	INTERMEDIATE
Steady Flow		
Surges		
Down to Nothing		
Nothing	X	X
Gas		
Gas & Water		
Water		

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR _____ FRESH _____ SALTY _____ SULFUR _____ BLACK _____

5 MINUTE SHUT-IN PRESSURE BRADENHEAD 0 INTERMEDIATE 0

REMARKS:

Producing during test. BH + INT through 1" fillings. Nothing on BH when opened, Nothing on
Int when opened. Same after 5min shutin on both.

By [Signature]
Lease Operator
(Position)

Witness [Signature]

E-mail address bhanks@logosresourcesllc.com