NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
http://emnrd.state.nm.us/ocd/District III/3distric.htm

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 4 JUNE 2018 Operator HILCORP API #30-039-24615

Property Name SANJUAN 30-6 Well No. 402 Location: Unit ___ Section 15 Township 30 Range 7

Well Status(Shut-In or Producing) Initial PSI: Tubing 70 Intermediate N/A Casing 70 Bradenhead 7

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

PRESSURE

Testing	Bradenhead BH	Bradenhead Int	Bradenhead Csg	INTERM Int	INTERM Csg
TIME 5 min	0	N/A	70		
10 min	0		70		
15 min	0		70	N/A	
20 min					
25 min					
30 min					

FLOW CHARACTERISTICS

	BRADENHEAD	INTERMEDIATE
Steady Flow		
Surges		
Down to Nothing	X	
Nothing		N/A
Gas	X	
Gas & Water		
Water		

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR_____ FRESH_____ SALTY_____ SULFUR_____ BLACK_____

5 MINUTE SHUT-IN PRESSURE BRADENHEAD 0 INTERMEDIATE N/A

REMARKS: OPENED THE BRADENHEAD AND IT BED DOWN IN 5 SECONDS.

By [signature]

LEAD OPERATOR
(Position)

Witness [signature]

E-mail address _____

NMOCD
JUN 05 2018
DISTRICT III