



NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

NMOCD

JUN 05 2018

DISTRICT III

OIL CONSERVATION DIVISION

AZTEC DISTRICT OFFICE

1000 RIO BRAZOS ROAD

AZTEC NM 87410

(505) 334-6178 FAX: (505) 334-6170

[http://emnrd.state.nm.us/ocd/District III/3distric.htm](http://emnrd.state.nm.us/ocd/District%20III/3district.htm)

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 6-5-18 Operator Kimbell Quating API #30-0 45-05577

Property Name Hanson Well No. 1 Location: Unit 5 Section 5 Township 25 Range 10

Well Status (Shut-In or Producing) Initial PSI: Tubing 212 Intermediate VA Casing 236 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE			INTERM	
	BH	Bradenhead Int	Csg	Int	Csg
TIME					
5 min	<u>0</u>		<u>229</u>		
10 min	<u>0</u>		<u>229</u>		
15 min	<u>0</u>		<u>230</u>		
20 min					
25 min					
30 min					

FLOW CHARACTERISTICS	
BRADENHEAD	INTERMEDIATE
Steady Flow	
Surges	
Down to Nothing	
Nothing	<u>/</u>
Gas	
Gas & Water	
Water	

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR _____ FRESH _____ SALTY _____ SULFUR _____ BLACK _____

5 MINUTE SHUT-IN PRESSURE

BRADENHEAD 0

INTERMEDIATE VA

REMARKS:

dwdb w/p:ewr - do high level detection
off cycle - nothing when opened - nothing
when opened at 5 min shut-in

By Earl North

Witness Melissa Tuckling

(Position)

E-mail address _____