



NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6170 FAX: (505) 334-6170
<http://emrdd.state.nm.us/ocd/District/III/3distrct.htm>

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 5-3-18 Operator Vision Energy API #30-0 4520796

Property Name MSG Sec 18 Well No. 57 Location: Unit Section 7 Township 29 Range 16

Well Status (Shut-In or Producing) Initial PSI: Tubing 10 Intermediate Casing 6.2 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE			INTERM	
	BH	Bradenhead Int	Csg	Int	Csg
TIME					
5 min	0		6.2		
10 min	0		6.1		
15 min	0		6.0		
20 min					
25 min					
30 min					

FLOW CHARACTERISTICS	
BRADENHEAD	INTERMEDIATE
Steady Flow	
Surges	
Down to Nothing	
Nothing	✓
Gas	
Gas & Water	
Water	

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR FRESH SALTY SULFUR BLACK

5 MINUTE SHUT-IN PRESSURE BRADENHEAD 0 INTERMEDIATE

REMARKS: BH; Nothing when opened, nothing after 5 min. shut-in.

By John Wooten
Lease Operator
(Position)

Witness

E-mail address

NMOCD
MAY 21 2018
DISTRICT III