



NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
[http://emnr.state.nm.us/ocd/District III/3rdistrict.htm](http://emnr.state.nm.us/ocd/District%20III/3rdistrict.htm)

NMOC

JUN 11 2018

DISTRICT III

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 6-11-18 Operator Reliable Prod. LLC API #30-0 45-24044
Property Name San Jose de Cristo Well No. 25 Location: Unit D Section 34 Township 30 Range 11
Well Status (Shut-In or Producing) Initial PSI: Tubing 0 Intermediate N/A Casing 0 Bradenhead 35

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

PRESSURE

Testing	Bradenhead			INTERM	
	BH	Int	Csg	Int	Csg
TIME					
5 min	<u>6</u>		<u>0</u>		
10 min	<u>1</u>		<u>0</u>		
15 min	<u>0</u>		<u>0</u>		
20 min	<u>0</u>		<u>0</u>		
25 min	<u>0</u>		<u>0</u>		
30 min	<u>0</u>		<u>0</u>		

FLOW CHARACTERISTICS

BRADENHEAD INTERMEDIATE

Steady Flow /

Surges

Down to Nothing

Nothing

Gas /

Gas & Water

Water

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR _____ FRESH _____ SALTY _____ SULFUR _____ BLACK _____

5 MINUTE SHUT-IN PRESSURE

BRADENHEAD 0

INTERMEDIATE N/A

REMARKS:

Med blow when opened. - Still blowing at 15 min.
but 0 PSI - 20-25-30

By

Alan Pagan

Witness

Monica Kudilung

(Position)

E-mail address _____