



NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
[http://emrdr.state.nm.us/ocd/District III/3ddistrict.htm](http://emrdr.state.nm.us/ocd/District%20III/3ddistrict.htm)

NMOC

JUN 11 2018

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

DISTRICT III

Date of Test 6-11-18 Operator Reliable Prod. LLC API #30-0 45-25440

Property Name Hatch Well No. 1 Location: Unit C Section 11 Township 29 Range 15

Well Status (Shut-In or Producing) Initial PSI: Tubing 0 Intermediate ✓ Casing 1 Bradenhead 8

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

PRESSURE

Testing	Bradenhead			INTERM	
	BH	Int	Csg	Int	Csg
TIME					
5 min	<u>0</u>		<u>1</u>		
10 min	<u>0</u>		<u>1</u>		
15 min	<u>0</u>		<u>1</u>		
20 min					
25 min					
30 min					

FLOW CHARACTERISTICS

BRADENHEAD INTERMEDIATE

Steady Flow

Surges

Down to Nothing ✓

Nothing

Gas ✓

Gas & Water

Water

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR _____ FRESH _____ SALTY _____ SULFUR _____ BLACK _____

5 MINUTE SHUT-IN PRESSURE

BRADENHEAD 0

INTERMEDIATE ✓

REMARKS:

BH down to nothing in 18 seconds long
puff when opened after 5 min shut in

By Adrian Lopez

Witness Monica Cuchling

(Position)

E-mail address _____