



NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
[http://emrnr.state.nm.us/ocd/District III/3distric.htm](http://emrnr.state.nm.us/ocd/District%20III/3distric.htm)

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 5-22-18 Operator Juniper Resources API #30-0 30-045-74240
Property Name TAH TAH Well No. 26-1 Location: Unit 6 Section 76 Township 5N Range 10W
Well Status (Shut-In or Producing) Initial PSI: Tubing 100 Intermediate Casing 59 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE				
	Bradenhead	INTERM			
	BH	Int	Csg	Int	Csg
TIME					
5 min	<u>0</u>		<u>59</u>		
10 min	<u>0</u>		<u>59</u>		
15 min	<u>0</u>		<u>59</u>		
20 min					
25 min					
30 min					

FLOW CHARACTERISTICS	
BRADENHEAD	INTERMEDIATE
Steady Flow	
Surges	<u>HMCCD</u>
Down to Nothing	<u>JUN 08 2018</u>
Nothing <u>X</u>	<u>DISTRICT III</u>
Gas	
Gas & Water	
Water	

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR FRESH SALTY SULFUR BLACK

5 MINUTE SHUT-IN PRESSURE BRADENHEAD 0 INTERMEDIATE

REMARKS:

well is producing, nothing on bradenhead

By Billy K. Hoss

Witness

Lease operator
(Position)

E-mail address