



NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
[http://emrnr.state.nm.us/ocd/District III/3district.htm](http://emrnr.state.nm.us/ocd/District%20III/3district.htm)

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 5-24-18 Operator Juniper Resources API #30-0 30-045-35442

Property Name Pinon Unit Well No. 3074 Location: Unit L Section 10 Township 24N Range 10W

Well Status (Shut-In or Producing) Initial PSI: Tubing 94 Intermediate Casing 77 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE				
	BH	Bradenhead		INTERM	
		Int	Csg	Int	Csg
TIME					
5 min	<u>0</u>		<u>77</u>		
10 min	<u>0</u>		<u>77</u>		
15 min	<u>0</u>		<u>77</u>		
20 min					
25 min					
30 min					

FLOW CHARACTERISTICS	
BRADENHEAD	INTERMEDIATE
Steady Flow	
Surges	<u>NMOCB</u>
Down to Nothing	<u>JUN 08 2018</u>
Nothing <u>X</u>	<u>DISTRICT III</u>
Gas	
Gas & Water	
Water	

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR FRESH SALTY SULFUR BLACK

5 MINUTE SHUT-IN PRESSURE BRADENHEAD 0 INTERMEDIATE

REMARKS:

well is producing nothing on bradenhead

By Billy Joe Hess
Lease Operator
(Position)

Witness

E-mail address