



NEW MEXICO ENERGY, MINERALS & NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
[http://emnr.state.nm.us/ocd/District III/district.htm](http://emnr.state.nm.us/ocd/District%20III/district.htm)

NMOC

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

JUN 27 2018

Date of Test 6-27-2018 Operator Hilcorp Energy Co. API #30-0 45 067 911

Property Name CM Morris Well No. 4 Location: Unit Section 13 Township 27 Range 10

Well Status(Shut-In or Producing) Initial PSI: Tubing 4 Intermediate 0 Casing 4 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE			INTERM	
	BH	Bradenhead Int	Csg	Int	Csg
TIME					
5 min	0	0	4	0	4
10 min	0	0	4	0	4
15 min	0	0	4	0	4
20 min					
25 min					
30 min					

FLOW CHARACTERISTICS	
BRADENHEAD	INTERMEDIATE
Steady Flow	
Surges	
Down to Nothing	
Nothing	X
Gas	
Gas & Water	
Water	

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR FRESH SALTY SULFUR BLACK

5 MINUTE SHUT-IN PRESSURE

BRADENHEAD 0

INTERMEDIATE 0

REMARKS:

Nothing on BH when opened. Nothing on BH after 5min shut in -
Nothing on intermediate when opened - Nothing on intermediate after 5min
shut in

By [Signature]

Witness [Signature] NMOC

(Position)

E-mail address