

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised April 3, 2017

Submit 1 Copy to appropriate District Office in accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

OPERATOR

Subsequent Report Final Report

Name of Company Hilcorp Energy Company	Contact Jennifer Deal
Address 382 Road 3100, Aztec, NM 87410	Telephone No. (505) 324-5128
Facility Name Standard 1	Facility Type Gas Well

Surface Owner Federal	Mineral Owner	API No. 30-045-08718
-----------------------	---------------	----------------------

LOCATION OF RELEASE

Unit Letter J	Section 04	Township 29N	Range 12W	Feet from the 1850	North/South Line South	Feet from the 1500	East/West Line East	County San Juan County
---------------	------------	--------------	-----------	--------------------	------------------------	--------------------	---------------------	------------------------

Latitude 36.7536011 Longitude -108.1002121 NAD83

NATURE OF RELEASE

Type of Release Produced Water/Hydrocarbon	Volume of Release Unknown	Volume Recovered none
Source of Release Dump Line to Tank	Date and Hour of Occurrence Unknown	Date and Hour of Discovery 11/28/17 @ 10:15am
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Cory Smith & Vanessa Fields & Whitney Thomas	
By Whom? Jennifer Deal	Date and Hour 11/29/17 @ 9:07am	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*



Describe Cause of Problem and Remedial Action Taken.*

Operator discovered historic contamination while digging up the dump line to the tank.

Describe Area Affected and Cleanup Action Taken.*

Hilcorp Energy Company is assessing options for the path forward and will submit another update by June 15, 2018.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 	OIL CONSERVATION DIVISION	
Printed Name: Jennifer Deal	Approved by Environmental Specialist 	
Title: Environmental Specialist	Approval Date: 5/31/18	Expiration Date:
E-mail Address: jdeal@hilcorp.com	Conditions of Approval:	Attached <input checked="" type="checkbox"/>
Date: 5/16/18	Phone: (505) 324-5128	

* Attach Additional Sheets If Necessary

NCS1735235018

Fields, Vanessa, EMNRD

From: Fields, Vanessa, EMNRD
Sent: Thursday, May 31, 2018 10:44 AM
To: 'Jennifer Deal'
Cc: Smith, Cory, EMNRD
Subject: RE: Subsequent C-141 Standard 1

Good morning Jennifer,

HilCorps Subsequent C-141 submitted for the Standard #001 has been approved with the following conditions of approval.

- Following the NMOCD Guidelines for Remediation's of Leaks, Spills and Releases the remediation's levels for the **Standard #001** soils at the are as follows: 10 mg/kg Benzene, 50 mg/kg BTEX and 100 mg/kg TPH.
- A soil remediation plan shall be submitted to the OCD by 6/15/2018 detailing HilCorps remediation plan.
- A groundwater sample will be collected from the identified source area by 6/15/2018 and analyzed with method 8260.
- • **Provide OCD District III office 24 hour notification prior to sampling.**

Please let me know if you have any questions.

Thank you,

Vanessa Fields
Environmental Specialist
Oil Conservation Division
Energy, Minerals, & Natural Resources
1000 Rio Brazos, Aztec, NM 87410
(505)334-6178 ext 119
Cell: (505) 419-0463
vanessa.fields@state.nm.us

From: Jennifer Deal <jdeal@hilcorp.com>
Sent: Wednesday, May 16, 2018 3:46 PM
To: Fields, Vanessa, EMNRD <Vanessa.Fields@state.nm.us>; Smith, Cory, EMNRD <Cory.Smith@state.nm.us>
Subject: Subsequent C-141 Standard 1

Please accept the attached Subsequent C-141 for the Standard 1. I will put a paper copy in the mail today. Let me know if you have any questions.