



NEW MEXICO ENERGY, MINERAL
& NATURAL RESOURCES DEPARTMENT

NMOC

JUL 18 2018

DISTRICT III

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

OIL CONSERVATION DIVISION

AZTEC DISTRICT OFFICE

1000 RIO BRAZOS ROAD

AZTEC NM 87410

(505) 334-6178 FAX: (505) 334-6170

http://emnr.state.nm.us/ocd/District III/3district.htm

Date of Test 7-18-18 Operator Hilcorp Energy API #30-0 45-21042
Property Name Graveling A Well No. 7 Location: Unit 22 Township 28 Range 8
Well Status (Shut-In or Producing) Initial PSI: Tubing N/A Intermediate N/A Casing 7 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE			INTERM	
	BH	Bradenhead Int	Csg	Int	Csg
TIME					
5 min	<u>0</u>		<u>7</u>		
10 min	<u>0</u>		<u>7</u>		
15 min	<u>0</u>		<u>7</u>		
20 min					
25 min					
30 min					

FLOW CHARACTERISTICS	
BRADENHEAD	INTERMEDIATE
Steady Flow	
Surges	
Down to Nothing	<u>✓</u>
Nothing	
Gas	<u>✓</u>
Gas & Water	
Water	

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR _____ FRESH _____ SALTY _____ SULFUR _____ BLACK _____

5 MINUTE SHUT-IN PRESSURE

BRADENHEAD 0

INTERMEDIATE N/A

REMARKS:

Stimulated - Duff when opened - Nothing when
opened after 5 min shut-in

By Jennifer D. Dibley

Witness Norosa Kuehling

(Position)

E-mail address _____