



NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
[http://emnrd.state.nm.us/ocd/District III/3distr.htm](http://emnrd.state.nm.us/ocd/District%20III/3distr.htm)

NMOCd

JUL 20 2018

DISTRICT III

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 7-20-18 Operator MEG Drilling Co Inc API #30-0 45 25692
Property Name Horse Shoe Well No. 1 Location: Unit K Section 2 Township 29 Range 15
Well Status (Shut-In or Producing) Initial PSI: Tubing 6 Intermediate 1/4 Casing 6 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE				
	Bradenhead			INTERM	
	BH	Int	Csg	Int	Csg
TIME					
5 min	<u>0</u>		<u>7</u>		
10 min	<u>0</u>		<u>7</u>		
15 min	<u>0</u>		<u>7</u>		
20 min					
25 min					
30 min					

FLOW CHARACTERISTICS	
BRADENHEAD	INTERMEDIATE
Steady Flow	
Surges	
Down to Nothing	<u>✓</u>
Nothing	
Gas	<u>✓</u>
Gas & Water	
Water	

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR _____ FRESH _____ SALTY _____ SULFUR _____ BLACK _____

5 MINUTE SHUT-IN PRESSURE

BRADENHEAD 0

INTERMEDIATE 1/4

REMARKS:

Puff when opened - (nothing when opened
after 5 min shut in.

By [Signature]

Witness Monica Kuehling

(Position)

E-mail address _____