



NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

NMCOED

AUG 10 2018

DISTRICT III

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410

(505) 334-6178 FAX: (505) 334-6170
[http://emnr.state.nm.us/ocd/District III/3district.htm](http://emnr.state.nm.us/ocd/District%20III/3district.htm)

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 8-9-18 Operator DSR Operating LLC API #30-0 45-05369
Property Name Central B'st. Unit Well No. 48 Location: Unit I Section 17 Township 25 Range 12
Well Status (Shut-In or Producing) Initial PSI: Tubing 11 Intermediate Casing 11 Bradenhead 146

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE			INTERM	
	BH	Int	Csg	Int	Csg
TIME					
5 min	<u>4</u>		<u>9</u>		
10 min	<u>0</u>		<u>9</u>		
15 min	<u>0</u>		<u>9</u>		
20 min	<u>0</u>		<u>9</u>		
25 min	<u>0</u>		<u>9</u>		
30 min	<u>0</u>		<u>9</u>		

FLOW CHARACTERISTICS	
BRADENHEAD	INTERMEDIATE
Steady Flow <u>✓</u>	
Surges <u> </u>	
Down to Nothing <u> </u>	
Nothing <u> </u>	
Gas <u>✓</u>	
Gas & Water <u> </u>	
Water <u> </u>	

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR FRESH SALTY SULFUR BLACK

5 MINUTE SHUT-IN PRESSURE

BRADENHEAD 7

INTERMEDIATE ✓ 14

REMARKS:

Hard blow when opened - 5-10 -
to lighter blow 15-20-25-30

Gas samples taken on BH tubing. Prod. Casing

By Jacob Horter
Jacob Horter
(Position)

Witness Nomica Cukling

E-mail address jhorter@cottonwoodconsulting.com