



NEW MEXICO ENERGY, MINERALS and NATURAL RESOURCES DEPARTMENT

NMOCD

AUG 06 2018

MECHANICAL INTEGRITY TEST REPORT

(TA OR UIC)

Date of Test 8-6-2018 Operator Hilcorp API # 30-0 45-09619

Property Name WELL HALL Well # 1 Location: Unit 11 Sec 7 Twn 30 Rge 11

Land Type:

State _____
Federal _____
Private X _____
Indian _____

Well Type:

Water Injection _____
Salt Water Disposal _____
Gas Injection _____
Producing Oil/Gas X _____
Pressure observation _____

NMOCD
AUG 06 2018
DISTRICT 111

Temporarily Abandoned Well (N) Post Workover TA Expires: _____

Casing Pres. 0 _____
Bradenhead Pres. 0 _____
Tubing Pres. 0 _____
Int. Casing Pres. 0 _____

Tbg. SI Pres. _____
Tbg. Inj. Pres. _____

Max. Inj. Pres. _____

Pressured annulus up to 575 psi. for 35 mins. Test passed/failed failed

REMARKS: pressured up to 575 psi - Had lost approx 15 psi in first 10 min to 560 psi
down to 550 psi at 20 min - Held at 545 psi for last 10 min of test. Ran
over to get full 10 min hold.

By [Signature]
(Operator Representative)

Witness [Signature]
(NMOCD)

Consultant
(Position)

Revised 02-11-02