



NEW MEXICO ENERGY, MINERALS & NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO DRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
[http://emnrd.state.nm.us/ocd/District III3/district.htm](http://emnrd.state.nm.us/ocd/District%20III3/district.htm)

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 17 AUG 2018 Operator HILCORP API #30-0 45 09865

Property Name HAZEL BULACK F Well No. 1 Location: Unit _____ Section _____ Township _____ Range _____

Well Status(Shut-In or Producing) Initial PSI: Tubing 121 Intermediate N/A Casing 121 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE			INTERM	
	BH	Bradenhead Int	Csg	Int	Csg
TIME					
5 min	<u>0</u>	<u>N/A</u>	<u>121</u>		
10 min	<u>0</u>		<u>121</u>		
15 min	<u>0</u>		<u>121</u>		
20 min					
25 min					
30 min					

	FLOW CHARACTERISTICS	
	BRADENHEAD	INTERMEDIATE
Steady Flow		
Surges		
Down to Nothing		
Nothing	<u>X</u>	
Gas		
Gas & Water		
Water		

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR _____ FRESH _____ SALTY _____ SULFUR _____ BLACK _____

5 MINUTE SHUT-IN PRESSURE

BRADENHEAD 0

INTERMEDIATE N/A

REMARKS:

OPENED THE BRADENHEAD AND NOTHING CAME OUT

By

Witness

(Position)

NMOC

E-mail address _____

AUG 17 2018

DISTRICT III