



NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

EMNRD

AUG 10 2018

DISTRICT III

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410

(505) 334-6178 FAX: (505) 334-6170

[http://emnr.state.nm.us/ocd/District III/3district.htm](http://emnr.state.nm.us/ocd/District%20III/3district.htm)

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 8-9-18 Operator JSR Consulting LLC API #30-0 45-13282
Property Name Central Bistit Well No. 4 Location: Unit 6 Section 6 Township 25 Range 12
Well Status (Shut-In or Producing) Initial PSI: Tubing 21 Intermediate 11A Casing 24 Bradenhead 117

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE			INTERM	
	Bradenhead			Int	Csg
	BH	Int	Csg		
TIME					
5 min	<u>10</u>		<u>23</u>		
10 min	<u>5</u>		<u>23</u>		
15 min	<u>3</u>		<u>23</u>		
20 min	<u>2</u>		<u>23</u>		
25 min	<u>2</u>		<u>23</u>		
30 min	<u>1</u>		<u>23</u>		

	FLOW CHARACTERISTICS	
	BRADENHEAD	INTERMEDIATE
Steady Flow	<u>✓</u>	
Surges		
Down to Nothing		
Nothing		
Gas	<u>✓</u>	
Gas & Water		
Water		

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR FRESH SALTY SULFUR BLACK

5 MINUTE SHUT-IN PRESSURE

BRADENHEAD 28

INTERMEDIATE 11A

REMARKS:

Hard blow when opened. 5-10-15-20-25-30
Lighter blow at 20 min
Gas samples taken production casing & BH. 8-8-18

By Jacob Harter
Jacob Harter
(Position)

Witness Monica Kahlberg

E-mail address jharter@cottonwoodconsulting.com