



NEW MEXICO ENERGY, MINERALS & NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
[http://emnrd.state.nm.us/ocd/District III/district.htm](http://emnrd.state.nm.us/ocd/District%20III/district.htm)

NMOC

AUG 16 2018

DISTRICT III

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 8-15-18 Operator BP America API #30-0 45-26901

Property Name NEBU Well No. 404 Location: Unit E Section 34 Township 31 Range 7

Well Status(Shut-In or Producing) Initial PSI: Tubing 60 Intermediate NA Casing 0 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE			INTERM	
	BH	Bradenhead Int	Csg	Int	Csg
TIME					
5 min	—	NA	Ø		
10 min	—	—	Ø		
15 min	—	—	Ø		
20 min		—			
25 min		—			
30 min		—			

FLOW CHARACTERISTICS	
BRADENHEAD	INTERMEDIATE
Steady Flow	
Surges	
Down to Nothing	X
Nothing	
Gas	X
Gas & Water	
Water	

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR _____ FRESH _____ SALTY _____ SULFUR _____ BLACK _____

5 MINUTE SHUT-IN PRESSURE

BRADENHEAD Opsi

INTERMEDIATE NA

REMARKS:

Light blow to nothing when BH was opened. Blew down in aprox twenty seconds
Nothing on BH after five minute shut in.

By Mellor

Witness [Signature] NMOC

(Position)

E-mail address _____