



NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO DRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
[http://emnrd.state.nm.us/ocd/District III/district.htm](http://emnrd.state.nm.us/ocd/District%20III/district.htm)

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 20 AUG 2018 Operator HTL CORP API #30-0 45 32253

Property Name SAN JUAN 32-9 Well No. 2825 Location: Unit 32 Section 37 Township 32 Range 7

Well Status (Shut-In or Producing) Initial PSI: Tubing N/A Intermediate N/A Casing 600 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE			INTERM	
	BH	Int	Csg	Int	Csg
TIME					
5 min	0	N/A	600		
10 min	0		600		
15 min	0		600		
20 min					
25 min					
30 min					

FLOW CHARACTERISTICS	
BRADENHEAD	INTERMEDIATE
Steady Flow	
Surges	
Down to Nothing	
Nothing	
Gas	
Gas & Water	
Water	

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR _____ FRESH _____ SALTY _____ SULFUR _____ BLACK _____

5 MINUTE SHUT-IN PRESSURE _____ BRADENHEAD _____ INTERMEDIATE _____

REMARKS:

OPENED THE BRADENHEAD AND NOTHING
CAME OUT.

By [Signature]

Witness [Signature]

(Position)

E-mail address _____

NMOCD

AUG 20 2018

DISTRICT III